

<i>Issue Date</i>	<i>Org. Code</i>	<b>NATIONAL WEATHER SERVICE</b>	<i>Program</i>	<i>Part</i>	<i>Section</i>
	W/OPS12	<b>Engineering Division</b>	EHB-11	02	2.6

#### MAINTENANCE INDEX - AUTOMATED SURFACE OBSERVING SYSTEM

<b>Number</b>	<b>Date of Issue</b>	<b>Title</b>
1	April 8, 1992	Technical Information Package (TIP) for Automated Surface Observing System (ASOS)
2	May 15, 1992	Engineering Management Reporting System (EMRS) for ASOS
3	October 7, 1992	Hygrothermometer Configurations
4	January 22, 1993	Lightning Rod Safety Cover for Wind Sensor Tower
5	April 15, 1993	Paroscientific Model 760-16B Portable Pressure Standard
6	May 3, 1993	Pressure Sensor Maintenance Check
7	August 12, 1993	Setting up the Panasonic KX-P1180 and KX-P2180 Dot Matrix Printers
8	May 5, 1994	Resetting ASOS Pressure Sensors
9	<i>Not Issued</i>	Wind Direction Fixture
10	June 17, 1994	Calling the ASOS Operations and Monitoring Center (AOMC)
11	July 8, 1994	Correction for the Laser Beam Ceilometer Calibration Procedure
12	July 28, 1994	Alternative Battery Check Procedure for the Liquid Precipitation Accumulation Sensor (LPAS)
13	July 29, 1994	Functional Designations for the Fiber Optic Modem S100-2A3AI-I
14	October 11, 1994	Time Set for ASOS Every 90 days
15	<i>Deleted</i>	Reduction of Hygrothermometer Mirror-Cleaning Period
16	April 27, 1995	Errata Sheet #1 to provide additional information to Maintenance Note 16
16	March 31, 1995	Wind Direction Vane and Wind Speed Cup Assembly Skirt Clearance
17	April 27, 1995	Ordering ASOS Site Technical Manual and Changes from NLSC
17	December 2, 1996	Errata Sheet #1 to provide corrections to Maintenance Note 17
17	June 30, 1997	Errata Sheet #2 to provide additional information to Maintenance Note 17

<i>Issue Date</i>	<i>Org. Code</i>	<b>NATIONAL WEATHER SERVICE</b>	<i>Program</i>	<i>Part</i>	<i>Section</i>
	W/OPS12	<b>Engineering Division</b>	EHB-11	02	2.6

<b>Number</b>	<b>Date of Issue</b>	<b>Title</b>
17	October 23, 1998	Errata Sheet #3 to provide additional corrections to Maintenance Note 17
18	December 4, 1995	Errata Sheet #1 to update Maintenance Note 18
18	February 4, 2000	Errata Sheet #3 to update Maintenance Note 18
18	June 20, 1997	Errata Sheet #2 to update Maintenance Note 18
18	May 5, 1995	ASOS Spares Kit
19	September 7, 1995	Setting up the Panasonic KX-P3123 Impact Dot Matrix Printers
20	<i>Not Issued</i>	Freezing Rain Sensor Field Calibration
21	September 9, 1996	Autobalance Module Threshold Resistor (R5)
22	March 3, 1996	Frozen Wind and Direction Bottles
23	June 4, 1996	Dew Point Sensor Assembly Improvements
24	June 17, 1996	4-Wire to 2-Wire Telephone Circuit Remote for ASOS Equipment
25	October 21, 1996	Hygrothermometer Dew Point Sensor Mirror and Optical Loop Adjustment Maintenance
26	August 9, 1996	Freezing Rain Sensor Grounds
27	August 23, 1996	Ordering and Installing ASOS Calibration Software
28	September 27, 1996	Safe Operation of ASOS Freezing Rain Sensor
29	October 15, 1996	Accessing the ASOS Technical Information Center Home Page
30	October 17, 1996	Technical Information
31	January 30, 1997	Visibility Sensor Transmitter Optical Detector Functional Check
32	May 8, 1997	Safety Chain for an ASOS Hinged Sensor
33	<i>Not issued</i>	Ordering ASOS Site Technical Manual REV "A"
34	<i>Not Issued</i>	Thermostat Removal and Replacement
35	October 31, 1997	Assembly and Mounting of the Heated Enclosure for ASOS Testing (HEAT) for Cold and adverse Weather Maintenance on the ASOS Present Weather Sensor (Light Emitting Diode Weather Identifier (LEDWI))

<i>Issue Date</i>	<i>Org. Code</i>	<b>NATIONAL WEATHER SERVICE</b>	<i>Program</i>	<i>Part</i>	<i>Section</i>
	W/OPS12	<b>Engineering Division</b>	EHB-11	02	2.6

<b>Number</b>	<b>Date of Issue</b>	<b>Title</b>
36	<i>Not Issued</i>	OID Removal
37	December 17, 1997	ASOS S100 Site Technical Manual on CD-ROM
38	January 20, 1998	Resetting the ASOS Voice Broadcast at ATCT
39	July 2, 1999	Errata Sheet #1 to Add Sites to Maintenance Note 39
39	June 5, 1998	ASOS Freezing Rain Sensor Deactivation/Activation
39	September 20, 1999	Errata Sheet #2 to Delay Reactivation in Maintenance Note 39
40	May 12, 1998	Ordering the ASOS Site Technical Manual, Change 1, January 1998
41	July 15, 1998	Surge Protector for Peripheral Equipment
42	August 5, 1998	Interface Connection for the ATIS and ASOS at Unstaffed and Part-Time ATCT
42	May 3, 1999	Errata Sheet #1 to perform Voice Recorder/Playback Board Checks in Maintenance Note 42
42	September 14, 1999	Errata Sheet #2 to provide additional clarification to Maintenance Note 42
43	August 6, 1998	Procedural Reminder for Before and After Preventive and Corrective Maintenance Actions
44	October 8, 1998	Ordering the ASOS Site Technical Manual, Revision A, Change 1 on CD-ROM
45	October 22, 1998	Thumb Screws for the LEDWI Calibration Tube
46	June 25, 1999	Uninterruptible Power Supply (UPS) Configuration Table
46A	March 31, 2003	UPS Configuration Table Update
47	December 21, 1999	Ordering the ASOS STM Change Pages from NLSC
48	June 28, 2000	Installing the ASOS Insect Skirt
49A	December 20, 2002	ASOS NGRVR Information
50	<i>On Hold</i>	Verifying 1088/HO83 Readings
51	July 11, 2001	Unauthorized Modifications to ASOS
52	May 08, 2002	Installing Procomm Plus 4.7 under Windows 2000/XP

<i>Issue Date</i>	<i>Org. Code</i>	<b>NATIONAL WEATHER SERVICE</b>	<i>Program</i>	<i>Part</i>	<i>Section</i>
	W/OPS12	<b>Engineering Division</b>	EHB-11	02	2.6

<b>Number</b>	<b>Date of Issue</b>	<b>Title</b>
53	March 20, 2003	Closing ASOS Trouble Tickets via NOAA E-Mail